

Play Areas - Sites due for Inspection

Monthly Operational

Site 5905 Willand
Gables Lea

Inspected on 19/07/23
(date/time) by 11.10.HW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Fence	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate Pedestrian x 2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Goals 2 sets	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin Topsy	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Multi Play Unit	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roundabout	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Seat Stnd Plastic	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~Adrian Cook 07967179676~~

Play Areas - Sites due for Inspection

Monthly Operational

Site 6501 Willand
Mobile 01

Inspected on 19/07/23
(date/time) by 11.35.MU

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Fun Box	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign In Line Skating Safety	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~Adrian Cook 07967179676~~

Play Areas - Sites due for Inspection

Monthly Operational

Site 6502 Mobile
Mobile 02

Inspected on 19/07/27
(date/time) by 11.30-NE

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Grinding Box	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign In Line Skating Safety	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~Admin Contact 07967179676~~

Play Areas - Sites due for Inspection

Monthly Operational

Site 6503 Mobile
 Mobile 03
 Inspected on 19/07/23
 (date/time) by 11.20-nw

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Launch Ramp	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign In Line Skating Safety	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~Adrian Cook 07967179676~~

~~NEW EQUIPMENT~~

Play Areas - Sites due for Inspection

Monthly Operational

Site 5906 Willand
Chestnut Drive

Inspected on 19/07/23
(date/time) by 10-20-110

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Fence	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate Pedestrian x 2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin Guppy	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Multi Play Unit Senior	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Seat Other Plastic	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign No Ball Games	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Cradle	<input checked="" type="checkbox"/>	1x BRACKET LOOSE REPORTED TO P.C 19-07-23	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Flat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

HOWABOUT
SWINGS
MULTI PLAY UNIT

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~Adrian Cook 07967179676~~

Play Areas - Sites due for Inspection

Monthly Operational

Site 5901 Willand
South View

Inspected on 19/07/23
(date/time) by 11.10.MW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Fence Bow Top	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate Pedestrian x1	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin Guppy	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Multi Play Unit /Slide	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spring Mobile Cat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spring Mobile Dog	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Cradle	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~Adrian Cook 07967178876~~

Play Areas - Sites due for Inspection

Monthly Operational

Site 5908 Willand
Worcester Crescent

Inspected on 9/07/23
(date/time) by 08-45-nw

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Bench Plastic	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fence	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate pedestrian	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate vehicular	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Multi Play Unit /Slide	<input checked="" type="checkbox"/>	MONITOR THE STEPS BOTTOM STEP RUSTING AND METAL PAELING (PHOTO TAKEN)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
See Saw	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign No Ball Games	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Cradle	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~Adrian Cook 07967179676~~

Play Areas - Sites due for Inspection

Monthly Operational

Site 5909 Willand
Mallow Court

Inspected on 19/07/23
(date/time) by 08.10.MW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Bench Plastic x2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fence	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate Pedestrian x 2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate vehicular	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin Topsy	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Multi Play Unit /Slide	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spring Mobile Horse	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Cradle	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~XXXXXXXXXXXX~~

Play Areas - Sites due for Inspection

Monthly Operational

Site 5902 Willand
The Orchards

Inspected on 19/05/23
(date/time) by 09.50 - MW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Climbing Frame Ladder	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Dynamo Amazon Basin	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fence	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate Pedestrian x 2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate vehicular	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Goals 1 Set	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin Topsy	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Picnic Table Plastic	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
See Saw Gull Wing	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard x 2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Flat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~Adrian Cook 07967179676~~

Play Areas - Sites due for Inspection

Monthly Operational

Site 5920 Willand
Gables Lea (Parish Equipment)

Inspected on 19/07/23
(date/time) by 11:40 MW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Basket Ball	<input checked="" type="checkbox"/>	EMAIL SENT 19-07-23 @ 11:53 WOODEN BACK BOARD ROTTEN	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
BMX Track	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Climbing Frame Metal	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Picnic Bench	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
See Saw	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spring Mobile Elephant	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spring Mobile Horse	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Cradle	<input checked="" type="checkbox"/>	EMAIL SENT @ 11:53 1X SHOCKE BADLY WORN REQUIRES REPAIR OR REPLACE	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Swing Double Flat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Four Flat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Tarmac Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~07967179676~~

Teen Shelter



Trim Trail



Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 ~~Adrian Cook 07967179676~~