

Play Areas - Sites due for Inspection

Monthly Operational

Site 5901

Willand

South View

Inspected on

22/05/23

(date/time) by

12-48-MU

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Fence Bow Top	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate Pedestrian x1	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin Guppy	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Multi Play Unit /Slide	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spring Mobile Cat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spring Mobile Dog	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Cradle	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Adrian Cook 07967179676

Play Areas - Sites due for Inspection

Monthly Operational

Site 5908 Willand
Worcester Crescent

Inspected on 22/05/23
(date/time) by 11-50-MW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Bench Plastic	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fence	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate pedestrian	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate vehicular	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin	<input checked="" type="checkbox"/>	LITTER BIN FULL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Multi Play Unit /Slide	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
See Saw	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign No Ball Games	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Cradle	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Adrian Cook 07967179676

Play Areas - Sites due for Inspection

Monthly Operational

Site 5906 Willand
Chestnut Drive

Inspected on 18/05/23
(date/time) by 12-35-MLW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Fence	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate Pedestrian x 2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin Guppy	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Multi Play Unit Senior	<input type="checkbox"/>	REMOVED BY M.D.D.C	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Seat Other Plastic	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign No Ball Games	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Cradle	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Flat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Adrian Cook 07967179676

Play Areas - Sites due for Inspection

Monthly Operational

Site 5902 Willand
The Orchards

Inspected on 19/05/23
(date/time) by 12.05.MU

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Climbing Frame Ladder	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Dynamo Amazon Basin	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fence	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate Pedestrian x 2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate vehicular	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Goals 1 Set	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin Topsy	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
See Saw Gull Wing	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard x 2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Flat	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Adrian Cook 07967179676

Play Areas - Sites due for Inspection

Monthly Operational

Site 6503

Mobile

Mobile 03

Inspected on

22/05/23

(date/time) by

12.40 MW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Launch Ramp	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign In Line Skating Safet	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Adrian Cook 07967179676

Play Areas - Sites due for Inspection

Monthly Operational

Site 6502

Mobile

Mobile 02

Inspected on

22/05/23

(date/time) by

12-30-MW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Grinding Box	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign In Line Skating Safet	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Adrian Cook 07967179676

Play Areas - Sites due for Inspection

Monthly Operational

Site 6501 Willand
Mobile 01

Inspected on 22/05/23
(date/time) by 1225-110

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Fun Box	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign In Line Skating Safet	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Adrian Cook 07967179676

Play Areas - Sites due for Inspection

Monthly Operational

Site 5905

Willand

Gables Lea

Inspected on

22/05/23

(date/time) by

11-55-FL

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Fence	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gate Pedestrian x 2	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Goals 2 sets	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Litter Bin Topsy	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Multi Play Unit	<input checked="" type="checkbox"/>	SOME VERY SMALL DAMAGED TO THE SURF SHATE [PHOTO TAKEN] NO SHARP EDGES MONITOR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roundabout	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input type="checkbox"/>	CHALK DRAWING ON THE SURFACE NOTHING OFFENSIVE SHOULD WASH OFF WHEN IT RAINS (JUST NOTED)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Seat Stnd Plastic	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sign Standard	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Adrian Cook 07967179676

Play Areas - Sites due for Inspection

Monthly Operational

Site 5920 Willand
Gables Lea (Parish Equipment)

Inspected on 24/05/23
(date/time) by 11-55-MW

Equipment	Inspected	Defect	Risk			
			Low	Med	High	Imm
Basket Ball	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
BMX Track	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Climbing Frame Metal	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miscellaneous Items	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Picnic Bench	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety Surface	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
See Saw	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spring Mobile Elephant	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spring Mobile Horse	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Cradle	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Double Flat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Swing Four Flat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Tarmac Surface	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967479681 Adrian Cook 07967179676

Teen Shelter

<input checked="" type="checkbox"/>							
-------------------------------------	--	--	--	--	--	--	--

Trim Trail

<input checked="" type="checkbox"/>							
-------------------------------------	--	--	--	--	--	--	--

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Adrian Cook 07967179676